

Rot Repair:

Weathervane Wood Window Sill



One third of the sill on this window was rotten and soft to the touch.

After removing the window sash, we cut and removed the rotten wood, leaving behind only what was still solid.



Fir has been cut to fit, primed, then screwed (not nailed) solidly to the existing frame.



Finally, we caulk all seams, putty over the screws and reinstall the Weathervane Window Sash (new glass installed as well). The sill and frame is now ready to be painted.

